

**ROTO ROOTER
PO BOX 3154
BISMARCK ND 58502
701-222-2653**

Pipe Inspection Summary for Project: MIDWAY 14TH ADDITION

Printed: August 5, 2015 11:30am

SUMMARY INFORMATION

Total Number of Pipes	1
Total Pipe Footage	311.40
Total Inspected Pipe Footage	311.40
Total Uninspected Pipe Footage	0.00
Average Pipe Length	311
Total Estimated Pipe Joints	77
Total Number of Observations	6
Total Inch-Diameter-Miles	0.6
Total Leak Rate (gpm)	0.0
Leakage Rate Per IDM	0.00

Pipe Filter for this Report (if any):

FREQUENCY COUNT BY OBSERVATION

<u>Observation</u>	<u>Count</u>
Manhole, Downstream	1
Manhole, Upstream	1
Service, Connection	4
Total Observation Count	6

**ROTO ROOTER
PO BOX 3154
BISMARCK ND 58502
701-222-2653**

Pipe Inspection Summary for Project: MIDWAY 14TH ADDITION

Printed: August 5, 2015 11:30am

PIPE FOOTAGE BY TYPE, MATERIAL, AND SIZE

SANITARY SEWER - <No Shape>

<u>Material</u>	<u>Size</u>	<u>Footage</u>
PVC	8.0	311.4
		311.4

Sanitary Sewer Total 311.4

Total All Pipe Types 311.4

**ROTO ROOTER
PO BOX 3154
BISMARCK ND 58502
701-222-2653**

Pipe Inspection Summary for Project: MIDWAY 14TH ADDITION

Printed: August 5, 2015 11:30am

PIPE FOOTAGE BY TYPE, SIZE, AND MATERIAL

SANITARY SEWER - <No Shape>

<u>Size</u>	<u>Material</u>	<u>Footage</u>
8.0	PVC	311.4
		311.4
Sanitary Sewer Total		311.4
Total All Pipe Types		311.4

**ROTO ROOTER
PO BOX 3154
BISMARCK ND 58502
701-222-2653**

Pipe Inspection Summary for Project: MIDWAY 14TH ADDITION

Printed: August 5, 2015 11:30am

PIPE COUNT AND FOOTAGE BY CONDITION RATING

SANITARY SEWER

Condition	Rating	Pipe Count	Footage
Hydraulic	<Unknown>	1	311.4
Infiltration	<Unknown>	1	311.4
Maintenance	<Unknown>	1	311.4
Structural	<Unknown>	1	311.4

Filter for this Report: