

**ROTO ROOTER  
PO BOX 3154  
BISMARCK ND 58502  
701-222-2653**

**Pipe Inspection Summary for Project: WACHERS 24TH ADD.**

Printed: August 5, 2015 11:34am

**SUMMARY INFORMATION**

Total Number of Pipes .....	2
Total Pipe Footage .....	471.40
Total Inspected Pipe Footage .....	471.40
Total Uninspected Pipe Footage .....	0.00
Average Pipe Length .....	236
Total Estimated Pipe Joints .....	117
Total Number of Observations .....	12
Total Inch-Diameter-Miles .....	0.9
Total Leak Rate (gpm) .....	0.0
Leakage Rate Per IDM .....	0.00

Pipe Filter for this Report (if any):

**FREQUENCY COUNT BY OBSERVATION**

<u>Observation</u>	<u>Count</u>
Manhole, Downstream .....	2
Manhole, Upstream .....	2
Service, Connection .....	8
<b>Total Observation Count</b>	<b>12</b>

**ROTO ROOTER  
PO BOX 3154  
BISMARCK ND 58502  
701-222-2653**

**Pipe Inspection Summary for Project: WACHERS 24TH ADD.**

Printed: August 5, 2015 11:34am

**PIPE FOOTAGE BY TYPE, MATERIAL, AND SIZE**

**SANITARY SEWER - <No Shape>**

<b>Material</b>	<b>Size</b>	<b>Footage</b>
PVC	8.0	471.4
		<b>471.4</b>

---

**Sanitary Sewer Total 471.4**

---

**Total All Pipe Types 471.4**

**ROTO ROOTER  
PO BOX 3154  
BISMARCK ND 58502  
701-222-2653**

**Pipe Inspection Summary for Project: WACHERS 24TH ADD.**

Printed: August 5, 2015 11:34am

**PIPE FOOTAGE BY TYPE, SIZE, AND MATERIAL**

**SANITARY SEWER - <No Shape>**

<b>Size</b>	<b>Material</b>	<b>Footage</b>
8.0	PVC	471.4
		<b>471.4</b>
<b>Sanitary Sewer Total</b>		<b>471.4</b>
<b>Total All Pipe Types</b>		<b>471.4</b>

**ROTO ROOTER  
PO BOX 3154  
BISMARCK ND 58502  
701-222-2653**

**Pipe Inspection Summary for Project: WACHERS 24TH ADD.**

Printed: August 5, 2015 11:34am

**PIPE COUNT AND FOOTAGE BY CONDITION RATING**

**SANITARY SEWER**

<b>Condition</b>	<b>Rating</b>	<b>Pipe Count</b>	<b>Footage</b>
Hydraulic	<Unknown>	2	471.4
Infiltration	<Unknown>	2	471.4
Maintenance	<Unknown>	2	471.4
Structural	<Unknown>	2	471.4

**Filter for this Report:**